Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	101	(monitor monitoring) with variation with film with thickness	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:04
L2	3	(monitor monitoring) with variation with film with thickness with group with workpiece	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:05
L3	3	(monitor monitoring) with variation with film with thickness and (group with workpiece) and subgroup	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:06
L4	3	(monitor monitoring) with variation with film with thickness and (group with workpiece) and subgroup and (calculate calculating calculation calculated)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:08
L5		(monitor monitoring) with variation with film and thickness and (group with workpiece) and subgroup and (calculate calculating calculation calculated)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:08
L6	3	(monitor monitoring) with variation and film and thickness and (group with workpiece) and subgroup and (calculate calculating calculation calculated)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:09
L7	. 3	(monitor monitoring) with film with thickness and (group with workpiece) and subgroup and (calculate calculating calculation calculated) and variation	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:09
L8	3	(monitor monitoring) and (film with thickness) and (group with workpiece) and subgroup and (calculate calculating calculation calculated) and variation	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:10
L9	13	(monitor monitoring) and film and (thick thickness) and group and workpiece and subgroup and (calculate calculating calculation calculated) and variation	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:17
L10	. 3	(monitor monitoring) with film and (thick thickness) and group and workpiece and subgroup and (calculate calculating calculation calculated) and variation	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:11

L11	. 3	(monitor monitoring) with (thick thickness) and film and group and workpiece and subgroup and (calculate calculating calculation calculated) and variation	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:11
L12	14	(monitor monitoring) and film and (thick thickness) and group and workpiece and subgroup and (calculate calculating calculation calculated)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:19
L13	14	(monitor monitoring) and film and (thick thickness) and workpiece and subgroup and (calculate calculating calculation calculated)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:20
L14	261	(monitor monitoring) with (thick thickness) and workpiece and (calculate calculating calculation calculated)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:21
L15	158	(monitor monitoring) with (thick thickness) and workpiece and (calculate calculating calculation calculated) and film	US-PGPUB; USPAT; EPO; DERWENT	OR .	ON	2005/02/18 16:22
L16	4	(monitor monitoring) with (thick thickness) with workpiece and (calculate calculating calculation calculated) and group and (sub-group subgroup) and film	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:22
L17	85	(monitor monitoring) with (thick thickness) and workpiece and (calculate calculating calculation calculated) and film and (group subgroup)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:23
L18	· 72	(monitor monitoring) with (thick thickness) and workpiece and (calculate calculating calculation calculated) and film and (group subgroup) and (select selecting selection selected) and (great greatest most maximum best)	US-PGPUB; USPAT; EPO; DERWENT	OR .	ON	2005/02/18 16:25
L19	61	(monitor monitoring) with (thick thickness) and workpiece and (calculate calculating calculation calculated) and film and (group subgroup) and (select selecting selection selected) and (great greatest most maximum best) and variation	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:25

L20	38	(monitor monitoring) with (thick thickness) and workpiece and (calculate calculating calculation calculated) and film and (group subgroup) and (select selecting selection selected) and (great greatest most maximum best) and variation and ((selected adj group) or (selected adj subgroup))	US-PGPUB; USPAT; EPO; DERWENT	OR .	ON	2005/02/18 16:26
L21	38	(monitor monitoring) with (thick thickness) and workpiece and (calculate calculating calculation calculated) and film and (group subgroup) and (select selecting selection selected) and (great greatest most maximum best) and variation and ((selected adj group) or (selected adj subgroup)) and range	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:26
L22	, 31	(monitor monitoring) with (thick thickness) and workpiece and (calculate calculating calculation calculated) and film and (group subgroup) and (select selecting selection selected) and (great greatest most maximum best) and variation and ((selected adj group) or (selected adj subgroup)) and range and standard	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:27
L23	4	(monitor monitoring) with (thick thickness) with workpiece and (calculate calculating calculation calculated) and film and (group subgroup) and (select selecting selection selected) and (great greatest most maximum best) and variation and ((selected adj group) or (selected adj subgroup)) and range and standard	US-PGPUB; USPAT; EPO; DERWENT	OR .	ON	2005/02/18 16:30
L24	2	(monitor monitoring) with (thick thickness) with workpiece and (calculate calculating calculation calculated) and film and (group subgroup) and (select selecting selection selected) and (great greatest most maximum best) and variation and ((selected adj group) or (selected adj subgroup)) and range and standard and subgroup	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/02/18 16:30